



Notice to Navigation Interests

US Army corps
Of Engineers
Buffalo District
1776 Niagara Street
Buffalo, New York 14207-3199

Notice No.


Date

Waterway


Lake Erie, Ohio

LRB-TD-ONS

Condition of Federal Navigation Channel Huron Harbor, Huron, Ohio

1. Dredging was performed within the Federal navigation Channel at Huron Harbor, Ohio during the month of July 2003. A survey was then performed in the area of the dredging only. The results of the survey are shown  pages 2 and 3 of 3.
2. Soundings are in feet and referred to Low Water Datum (LWD) 569.2 feet above Mean Water Level (MWL) at Rimouski, Quebec (International Great Lakes Datum 1985).
3. Vessel operators are advised to use caution when navigating in this area.
4. Copies of the sounding print for Huron Ohio consisting of (3) sheets, 03S-HUR-3/1 thru 3/3, at a cost of \$2.50 per sheet will be furnished upon receipt of a check in the full amount made payable to: United States Army Engineer District, Buffalo. Requests should be addressed to: District Commander, U.S. Army Engineer District, Buffalo, ATTN: NY/PA O&M Office, 1776 Niagara Street, Buffalo, New York 14207, requesting exact number or copies of sheets by file number. A point of contact and phone number must be indicated to facilitate response to the request. To obtain copies of the maps and other related materials, point your web browsers to <http://www.lrb.usace.army.mil/waterways/survey/survey.html>. Click on the link "SURVEY SECTION" to send a message containing your request.
5. Buffalo district's point of contact in reference to the exact number of sheets, file number, and the availability of any later information pertaining to the area is Mr. Kelly L. Maccarone, Chief of the Survey Section, Buffalo District, and may be contacted by phone at 716-879-4285.

WILLIAM H. TOWNSEND, P.E.
Chief, NY/PA Navigation and
Maintenance Section

REPORT OF CHANNEL CONDITIONS (FOR CHANNELS LESS THAN 400 FEET WIDE) (ER-1330-2-316)					PAGE 2 OF 3 PAGES		
					DATE		
TO: ACCOMPANY LOCAL NOTICE TO NAVIGATION INTERESTS, DATED				FROM: U.S. ARMY CORPS OF ENGINEERS, BUFFALO DISTRICT 1776 NIAGARA STREET, BUFFALO, NY 14207-3199 (716) 879-4292 FAX (716) 879-4356			
RIVER/HARBOR NAME AND STATE HURON HARBOR, HURON, OHIO					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (feet)	DEPTH (feet)			
(A) LAKE APPROACH CHANNEL.	JULY 2003	400	8400 (a)	29	24.0	26.1	23.4
(B) ENTRANCE CHANNEL, FROM LAKE APPROACH CHANNEL TO THE NORTH END OF THE EAST BREAKWATER.	JULY 2003	400-300	700	29	25.4	25.8	24.2
(C) ENTRANCE CHANNEL, FROM THE NORTH END OF THE EAST BREAKWATER TO SLIP #1.	JULY 2003	300 	1900	28	N/A	N/A	N/A
(D) HURON RIVER CHANNEL.	JULY 2003	120-350	1500	27	N/A	N/A	N/A
(E) TURNING BASIN	JULY 2003	0-400	600 (b)	21	N/A	N/A	N/A
REMARKS: (a) LENGTH VARIES DEPENDING ON THE LOCATION OF THE 29 FOOT CONTOUR IN LAKE ERIE. (b) IRREGULARLY SHAPED, SEE PROJECT CONDITION DRAWINGS.							

